

HOTFIX INFORMATION

Capture software version 4.0.4

Main fixes and optimizations between Capture v4.0.3 and Capture v4.0.4

- Warning popup on restart if touchscreen disabled
- Depth difference between inspection and analysis for twin crystal probes
- Capture PC install fail on specific versions of Windows 10

Known issues

- Data missed when changing gain during scanning
- Slow delay law computation for TFM with 5T and 5L modes

For any questions, remarks, or support needs, please contact us at support@eddyfi.com