

SIMS™ GO 1.2R2 Release Notes

Released: December 14, 2023

System Requirements

- Eddyfi Technologies FloormapX-AT for tank floor inspection.

Firmware

- Included with this release of SIMS™ GO, for FloormapX-AT:
 - Scanner Firmware Version 1.0R6.
 - Tablet Firmware version 1.0R3.

New Features and Improvements

- **C-scan Selection to Indication List:** Touching an indication on the C-scan view now selects the relevant indication within the Indication List.
- **Freescan Indication List:** Indication list is now also available with 'Freescan' mode.

Modifications to Existing Features

- Notifications are now displayed at the top right of screen.

Dropped Features

None in this version.

Resolved Issues

- Tablet freeze scenarios when navigation through plate views and changing plate.
- Scan speed not reset after battery change.

Known Issues, Limitations, and Restrictions

- Intermittent exclamation mark display on Plate Setup chevron after saving calibration.
- Overspeed warning is not visible during Calibration process.