

Eddyfi SIMS®GO 1.0R3 Release Notes

Released on: 12th April 2021

System Requirements

- Eddyfi FloormapX-AT for tank floor inspection.

Firmware

- Included with this release of SIMS®GO is package version 1.0R3 for FloormapX-AT

New Features and Improvements

None in this version

Modifications to Existing Features

None in this version

Dropped Features

None in this version

Resolved Issues

- Add Indication coordinate values incorrect when selecting a negative location with cursor before clicking add
- Software freeze if Start Acquisition fails
- Invalid Operation Detected after trying to scan over existing scan
- Invalid Operation Detected while navigating to T1-S1 in Scan view
- Cannot select scan in Plate view if indication is selected
- STARS view doesn't always show rendered data
- User Control Serial # and Scanner Head Serial # are wrong
- Sketch plate shows same track pattern as rectangular plate
- Missing Cursor in Endscan
- Unable to use magnet button after changing battery
- After disabling magnet, at scanner reboot magnet re-enables with no user warning
- UI not responding after scanner shuts down during Processing Scan operation
- Going to Freescan page causes small magnet shift while same calibration loaded
- Calibration Wizard menu displays indefinitely while removing battery from scanner

Known Issues, Limitations, and Restrictions

- Lower right keypad's "Maximize view" not implemented
- Exclamation mark display on Plate Setup chevron after creating a calibration
- If scanner is powered off, then powered on while tablet connected to it, OK fast bang does not respond correctly. Workaround : shortpress the tablet power button
- After disabling eStop, steering not responding
- Something a misleading "attempts to connect to the scanner had failed" appears at boot
- Indications pin is very small and can be difficult to hit
- Invalid Operation Detected while importing or loading calibration in inspection