

# Eddyfi SIMS®GO 1.0R4 Release Notes

Released on: 8<sup>th</sup> June 2021

## System Requirements

- Eddyfi FloormapX-AT for tank floor inspection.

## Firmware

- Included with this release of SIMS®GO is package version 1.0R4 for FloormapX-AT.

## New Features and Improvements

None in this version.

## Modifications to Existing Features

None in this version.

## Dropped Features

None in this version.

## Resolved Issues

- Remove time limit to get target speed.
- If tablet unplugged while in acquisition, scan page remains in acquisition mode.

## Known Issues, Limitations, and Restrictions

- Lower right keypad's "Maximize view" not implemented.
- Exclamation mark display on Plate Setup chevron after creating a calibration.
- If scanner is powered off, then powered on while the tablet is connected, software interaction thumbbutton does not respond correctly at all times. There is a workaround : shortpress the tablet power button and this will 'reset' for expected operation at all times.
- After disabling eStop, steering does not respond immediately.
- Upon turning the FloormapX on a notification can appear in the notification centre reporting "attempts to connect to the scanner had failed". All that is required is time to allow the connection.
- Invalid Operation Detected while importing or loading a calibration into an inspection.