

# ***Eddyfi SIMS®GO 1.3R2 Release Notes***

Released on: November 15, 2024

## ***System Requirements***

- Eddyfi FloormapX-AT for tank floor inspection.

## ***Firmware***

- Included with this release of SIMS®GO, for FloormapX-AT:
  - Scanner Firmware Version 1.0R7.
  - Tablet Firmware version 1.0R8.

## ***New Features and Improvements***

- **Tablet Firmware:** developments to the tablet firmware provide a more robust software update process and a reduction in component communication issues.
- **Software Update:** warnings associated with the PMU communication issue that arise will not prohibit data acquisition.

## ***Modifications to Existing Features***

- No modifications to existing features realised.

## ***Dropped Features***

- No features have been removed.

## ***Resolved Issues***

- **WiFi Detection:** addressed the issue where the tablet WiFi is not detected.

## ***Known Issues, Limitations, and Restrictions***

- **Historical Calibrations:** Calibrations created in previous software versions will not be compatible.
- Intermittent exclamation mark display on Plate Setup chevron after saving calibration.
- Overspeed warning is not visible during Calibration process.