M2M CAPTURE SOFTWARE VERSION 3.2.3

HOTFIX INFORMATION

Main fixes and optimizations between Capture v3.2.1 and Capture v3.2.3

- Incorrect depth readings (Mes-Ref)
- German translation
- Increase of the allowed distance between the TFM area and the probe
- Keyboard shortcut to the RMS software (Gekko/Mantis only): Ctrl + P
- Probe and scanner database updated (Silverwing, Ionix, M2M, …)
- Elementary A-Scans of a PWI inspection available in the Capture API
- Crash when exporting inspection report in .csv/.pdf format
- B-Scan and C-Scan views with SCUT application (Single Cristal UT) with 2-axis scanner
- 3D view optimized in motion and analysis
- Inverted probe on the 3D view with a raster trajectory

Known issues

- Un-zoom applied when moving mechanical cursor in analysis
- DGS/AVG instabilities
- Possible corrupted Capture files after an Ethernet transfer

For any questions, remarks or support needs, please contact us at support-m2m@eddyfi.com

© Eddyfi Technologies. All rights reserved.