

# SIMS<sup>®</sup> PRO 2.1R1 RELEASE NOTE

Released date: June 13<sup>th</sup> 2024

## New Database System

SIMS PRO 2.1 brings breaking changes to the way inspection databases work. Existing customers will have to convert their existing assets and inspections to the new database format.

Learn more about the changes and how to convert your inspections to the new format with our [SIMS PRO 2.1R1 video](#).

## New Features and Improvements

### New Database System

- Complete revamp of the inspection database system and file format.
- Support for remote workspace on company servers
- Addition of the Legacy Transfer tab in the backstage to enable conversion of legacy inspections into the new format
- Addition of the Remote Transfer tab in the backstage to copy inspections from local to remote and remote to local

### ECA Module

- Addition of an import and export function for ECA inspections
- In addition to notes, image attachments can now be added to indications, data files and components

## Resolved Issues

- Indication coordinates not updated when Plate is modified
- Hovering the cursor on an indication in Plate View doesn't always display information
- Patch Plate List table order by Plate ID is not instantly updating when numbering is changed
- Crash with a manual indication and "Save on Exit"
- Reportable properties still visible once the report has been closed
- Indication list not updating when view changed.
- Add manual indication not initially shown in indication list when open
- Properties not updating when device dropdown is changed
- Incorrect zoom level (fit) when entering plate view
- Indication Export button can become disabled.

## Known Issues, Limitations, Restrictions

- When loading existing report, it can sometimes display as blank