

# Eddyfi SIMS<sup>®</sup>PRO 2.0R1 Release Notes

Released on: May 16<sup>th</sup> 2023

## **\*\*\*New ECA Module\*\*\***

SIMS PRO 2.0 sees the addition of a new module for visualization and reporting of Eddy Current Array surface inspection data. This new module must be purchased separately from the baseline SIMS PRO. The standard version of SIMS PRO for storage tank bottom inspection is not mandatory to access the ECA Module.

To learn more about SIMSPRO ECA, please contact your Eddyfi Technologies sales representative.

## **New Features and Improvements**

- Addition of a new full-featured standalone module for Eddy Current Array and Magnifi data

## **Dropped Features**

- None in this release

## **Resolved Issues**

- Text box crashing when dragging box
- OTA updater crash message when updating from 1.1R5 to 1.2
- Unintentional rotation of manway on reports
- Invalid Operation Detected - When viewing a note marker attachment
- Export plate selection numbering not updating to match selection
- Memory usage increasing each time a report is generated
- Report Cover Image – JPG file not updating when selected
- Reportable Plate View numbering not updating to reflect layout
- Circular patch plate rotation remain 0 on annular ring
- Incorrect zoom level (fit) when entering plate view

## **Known Issues, Limitations, and Restrictions**