



M2M CAPTURE SOFTWARE VERSION 3.0.3

HOTFIX INFORMATION

List of the main fixes between Capture v3.0 and Capture v3.0.3

- Instabilities with fillet weld configurations
- Inch conversion issues
- German and Chinese translation update
- Incorrect delta cursor measurement
- Phoenix and Panametrics probe database update

List of new features

- TOFD band-pass and high-pass filters
- Multi-gates software alarms

List of remaining issues

- S-Scan display in DMA when rebound display
- Incorrect DMA focal law focusing points with multi-skews configurations

For any questions, remarks or support needs, please contact us at support-m2m@eddyfi.com