

HOTFIX INFORMATION

Capture software version 4.1.2

Main fixes and optimizations between Capture v4.1.2 and Capture v4.1.1

- High Amplitude on TFM files produced with Panther
- Instabilities with TFM Top view depth
- Auto-sizing with amplitude drop in TFM
- Index axis fixed with motorized scanner
- File merging issues
- Diverse instabilities

Known issues

- Data missed when changing gain during scanning
- Slow delay law computation for TFM with 5T and 5L modes

For any questions, remarks, or support needs, please contact us at support@eddyfi.com